

FIG. 1A




FIG. 1B




FIG. 2

FIG. 3 is a cross-sectional view of the device taken along the line 3-3 of FIG. 1, showing the internal components and the electrical connections.




FIG. 3




FIG. 4A




FIG. 4B




FIG. 6A




FIG. 6B




FIG. 8




FIG. 9

URL <http://www.maintain.co.jp/db/input.html>

TROUBLE DB INPUT WINDOW

DATE 404

MACHINE 401

FILE 403

S. N. S/N 402

EMERGENCY 405

STATE 406

SOLUTION 407

PROGRESS 408

410

[LINK TO RESULT LIST DATABASE](#)

[SOFTWARE LIBRARY](#) 411

[OPERATION GUIDE](#) 412

FIG. 10




FIG. II




FIG. 12